



# Calibrate your Thermometer



**Fill a container with crushed ice.**

**Add cold water.**



**Place thermometer into ice water.**

**Wait for the thermometer's needle or display area to stop moving.**

**Read the display area.**



**If the display area reads 32°F, the thermometer is accurate.**

**If not, adjust the nut with a wrench or other tool while the probe is in the ice bath until the display area registers 32°F.**